

NEW FOREST

Drainage work has been carried out on the 5th fairway and short of the greenside hazard.



Drainage work carried out on the 5th Fairway 18th February 2021



On the wet area short right of the bridge on the 5th hole the ground was taken away. The ground was then raised and replaced with stone and a mixture of sand and soil.